

# Release Notes for Version 1.1.0 of EmberEquine for Windows 10

March 2018

These notes provide important information for Juniper Systems release of the EmberEquine operating on any device running Microsoft Windows 10. These notes may also include important hardware information for the device.

Documentation and software updates are available from:

[www.junipersys.com/emberequine/support](http://www.junipersys.com/emberequine/support)

---

## Known Issues

These issues are open in this version of the software.

- EmberEquine can freeze or lock when setting a custom Wi-Fi access point name to the same name as an existing Wi-Fi access point (297)
  - Reports do not show results on a secondary contact (300)
  - Having more than one user logged into Windows and in EmberEquine on the same PC is not supported (286, & 282)
  - Vet reports are generated from the Cloud database. No Vet report will be generated if not logged into the cloud database (363)
  - When connection to the cloud is not ideal there are sometimes synchronization errors reported. It will synchronize when a link is reestablished (360)
  - The AP name shown in the upper left corner of the display is not always accurate. To check name, tap the Wi-Fi icon in the upper-left corner of the EmberEquine window to open the WiFi status screen. (353)
  - Multiple ultrasound images collected on an exam may not be able to be scrolled into view on the record details screen (from search). The user will have to enter edit mode to view all images. (296)
- 

PN 27689-01. © Copyright 2018. Juniper Systems, Inc. All rights reserved.

Windows is a registered trademark of Microsoft, Inc. in the United States and/or other countries.

Other trademarks in this document are the property of their respective owners.