

# Release Notes for Version 1.2 of EmberEquine for Windows 10

July 2018

These notes provide important information for Juniper Systems' release of EmberEquine Software operating on any device running Microsoft Windows 10. These notes may also include important hardware information for the device.

Documentation and software updates are available from:

[www.junipersys.com/emberequine/support](http://www.junipersys.com/emberequine/support)

---

## Updates and Resolved Issues

- Added screen to compare two ultrasound images into EmberEquine
- Added ability to save filters
- Added decimal as a new data field type
- Resolved issue where EmberEquine would freeze or lock when setting a custom Wi-Fi access point name to the same name as an existing Wi-Fi access point (297)
- Resolved multi user issues (286, & 282)
- Resolved User report issues (363)
- Resolved issue where the Access Point (AP) name shown in the upper left corner of the display was not accurate. To check name, tap the Wi-Fi icon in the upper-left corner of the EmberEquine window to open the WiFi status screen. (353)
- Resolved issue where multiple ultrasound images collected on an exam could not be navigated to on the record details screen. (296)

## Known Issues

These issues are open in this version of the software.

- Reports do not show results on a secondary contact (300)
  - When connection to the cloud is not ideal there are at times synchronization errors reported. It will synchronize when a link is re-established (360)
- 

PN 27689-02. © Copyright 2018. Juniper Systems, Inc. All rights reserved. Windows is a registered trademark of Microsoft, Inc. in the United States and/or other countries. Other trademarks in this document are the property of their respective owners.