

Field Applicator & Sensor Upgrade 2.1.3 Release Notes

Required Software

- Mirus 4.6.7
- Mirus GNSS Plugin 2.1.1

Required Actuator Firmware

Version 7.57.5

Updates

 Resolved an error that occurred when using Alvo Sensor with fewer than the maximum supported booms. (HYFA-207)

© Copyright Juniper Systems 11June2025. All rights reserved. All trademarks are registered or recognized by its respective owners. Specifications are subject to change without notice. JSPN 30787-04 · 435.753.1881 · 1132 W 1700 N · Logan, UT 84321 USA · junipersys.com

