Release Notes

OS Build 22292

For Mesa 3 Rugged Tablets Running the Windows 10 Operating System

These notes include important information for our Mesa 3 customers regarding the most recent release of the Mesa 3 Windows 10 operating system.

Documentation and software updates are located on our website here: *https://junipersys.com/support.*

Update Warnings

- You must update your device to BIOS 1.48 and EC 1.28 before installing OS 22292 or the OS patch.

- Batteries that have been updated will not work in units with an older BIOS and EC.

- The update may cause the following changes to the battery information in the Device Info app:
  - ▷ The battery disappears temporarily because the update failed or was interrupted.
  - ▷ The battery shows reduced capacity.
  - ▷ The battery shows reduced capacity but may get better with proper handling.
  - ▷ If you experience any of these conditions, reboot the device. If these conditions are present after the reboot, the battery is beyond the charge cycle life expectancy and will need to be replaced.

Updates in the OS for New Devices

- Graphics driver updated to 31.0.101.2111.
- Updated Device Information app to support the battery status.
- Updated the Battery Health driver.

Updates in the OS Patch

- Updated Device Information app to support the battery status.
- Updated the Battery Health driver.

JUNIPER®
S Y S T E M S