Release Notes for
Version 1.7.2 of Windows® Embedded Handheld 6.5 for the Allegro 2

January 2016

These notes provide important information for Juniper Systems release of the Microsoft Windows Embedded Handheld (formerly Windows Mobile) 6.5 operating system for the Allegro 2. These notes may also include important hardware information for the device.

Documentation and software updates are available from:

http://www.junipersys.com/Juniper-Systems/support

Contents

These release notes contain the following sections:

- Important Notes
- Known Issues
- Resolved Issues

Important Notes

- **Encrypted SD card cannot be used for OS update.** The device cannot perform an OS update with an SD card that has been encrypted. Before running an OS update, verify that the encryption option in Start > Settings > System > Encryption is disabled.

Known Issues

These issues are open in this version of the Operating System.

Battery / Charging

- Under some conditions the unit may wake from suspend while it is charging. [7348] Turn on auto suspend enabled so that it will return to suspend mode. Settings > system > power > advanced > On external power:

Resolved Issues

These issues are resolved in this version of the Operating System.

- The AKU was updated to integrate fixes from Microsoft, such as a fix to support SHA-2.
- An issue that caused the enter key to stop responding has been fixed. [7783]
- Updated GNSS control panel to handle differences between U-Blox and NVS GNSS receivers.
- Updated System control panel to indicate which receiver is detected.
- Updated JSNav to version 1.3.0 – translation updates for various languages (GNSS control panel and JSNAV).
- Added the ability to adjust the duration of the touchscreen disable notification.