# Release Notes for Version 1.6.2 of Windows<sup>®</sup> Embedded Handheld 6.5 for the Archer 2

July 2015

These notes provide important information for Juniper Systems release of the Microsoft Windows Embedded Handheld (formerly Windows Mobile) 6.5 operating system for the Archer 2. These notes may also include important hardware information for the device.

Documentation and software updates are available from:

http://www.junipersys.com/Juniper-Systems/support

### **Contents**

These release notes contain the following sections:

- Important Notes
- Known Issues
- Resolved Issues

## **Important Notes**

 Encrypted SD card cannot be used for OS update. The device cannot perform an OS update with an SD card that has been encrypted. Before running an OS update, verify that the encryption option in Start > Settings > System > Encryption is disabled. • Hardware OK button. The shift-5 button on the keypad can be used to send an "OK" to the application for screens that may not display an OK button and screens where the OK button does not work. This is most useful in applications that were designed for an earlier version of Windows Mobile, and it can also be found on some of the built-in applets.

# **Known Issues**

These issues are open in this version of the Operating System.

#### **Battery / Charging**

• Under some conditions the unit may wake from suspend while it is charging. [7348] Turn on auto suspend enabled so that it will return to suspend mode. Settings > system > power > advanced > On external power:

#### **Resolved Issues**

These issues are resolved in this version of the Operating System.

- Updated the barcode wedge software for slower key entry
- Updated setting for Wi-Fi/Bluetooth coexistence

PN 24286-04. © Copyright 2015. Juniper Systems, Inc. All rights reserved.

ActiveSync, Windows, and Windows Mobile are registered trademarks of Microsoft, Inc. in the United States and/or other countries.

Other trademarks in this document are the property of their respective owners.