


Release Notes

Product Update 1.0.3

For Geode Connect for iPhone and iPad



These notes include important information for Geode Connect for iPhone and iPad users regarding the most recent release of the app.

Documentation and software updates are located on the Juniper Systems website:

<https://www.junipersys.com/support>

Issues Resolved

- Geode Connect appears with the correct screen size on the iPhone XR. [GEODI-196]
- Issue that occurs with some NTRIP RTK networks requiring periodic GGA message updates has been addressed. [GEODI-192]
- The text in the Export Waypoints dialog box is now visible in later iOS versions. [GEODI-182]
- The home screen will show the correct SBAS option when a setting is changed. [GEODI-166, -177]
- Improved reconnection between the Geode and iOS device when the devices disconnect out of range. [GEODI-170, -186]
- An option is now available to abort the connection when the Geode is attempting to reconnect to an iOS device. [GEODI-171]
- iOS 15:
 - Display color defaults have changed to correct visibility issues. [GEODI-191]
 - The app crash event observed when swiping up from the bottom has been fixed. [GEODI-194]



tel: 435.753.1881 | web: www.junipersys.com

1132 W. 1700 N. Logan, UT 84321

PN 30332-01. Copyright© December 2021 Juniper Systems, Inc. All rights reserved. Information is subject to change without notice. Geode and Geode Connect are trademarks of Juniper Systems, Inc. iPhone and iPad are trademarks of Apple, Inc.